COUNTY OF VERMILION RIVER NO. 24 PROVINCE OF ALBERTA BY-LAW NO. 05-26

A BY-LAW	of the County of Vermilion River No. 24 in the Province of Alberta, to adopt the Devonia Lake West Central Area Structure Plan.	
WHEREAS	the Council of the County of Vermilion River No. 24 deems it to be in the public interest to adopt the Devonia Lake West Central Area Structure Plan;	
NOW THEREFORE	, be it resolved that the Council of the County of Vermilion River No. 24, duly assembled, hereby enacts that the Devonia Lake West Central Area Structure Plan, being Schedule "A" attached to and forming part of this By-Law, be adopted.	
THIS BY-LAW	shall take effect on the date of the third reading.	
READ A FIRST TIM	IE THIS 13 DAY OF December, A.D. 2005	
	In white	
	REEVE	
READ A SECOND	CÓUNTY ADMINISTRATOR TIME THIS DAY OF, A.D. 200_6	
	Son contlat	
	REEVE	
	COUNTY ADMINISTRATOR	
READ A THIRD TIME AND FINALLY PASSED THIS		
J	Dor whiteh	
	REEVE	
	COUNTY ADMINISTRATOR	

LakeView Estates Table of Contents

A) Development Concept & Servicing Plan

Transportation considerations Water Power / Phone Natural Gas Internal Road Structure Sewage System

- B) EUB History of Pipelines and Wells
- C) Farmland Assessment Rating
- D) Ground Water Potential Plan
- E) Natural Features
- F) Adjacent Land Uses
- G) Fire Protection
- H) School District
- I) Phase 1 Environmental Survey
- J) Storm Water Management Plan / Topographical Map
- K) Staging Plan/Signage

Development Concept and Servicing Plan

Based on the residents that occupy existing Multi-Parcel County Residential subdivisions, it is expected that this development with its close proximity to Lloydminster will also function as a "bedroom" community for the city.

Each land parcel will be used for a single family residential site. The development concept will act to restrict business, commercial or mixed use operations on the sites.

The conceptual diagram of the site indicates:

- 1) Land set aside as municipal reserve.
- 2) Environmental reserve along the lake shore.
- 3) The "U" shaped road pattern with multiple access to RR20. This feature gives emergency access should it be required.
- 4) Ponds to prevent silt from accessing the lake.

Transportation Considerations

With reference to the attached maps, the majority of the routing will be to Highway #16 or Highway #619 via RR20. Indications are RR20 may be paved in 2006 pending budget approvals (from Highway #16 to Highway #619)

With the future implementation of the Highway #16 bypass, the traffic patterns will change. The majority of residents will access the bypass Highway via an interchange on TWP RD 494. They would then come into Lloydminster from the South on Highway #17.

Water

Each home will be serviced via private wells with the cost and location being up to the home owner. Consulting with McAllister Water Well Drilling, 4 wells are adjacent to the property. They range in depth from 170 feet to 210 feet. These wells take from the same aquifer and depth differences are explained because of varying topography. They indicate volumes were of no concerns and quality was much better than experienced when compared to areas North of Highway #16. George McAllister's comment was "the poorest water in this area is better than the best water found North of Blackfoot".

Power / Phone

Each acreage lot will be serviced from Atco Power and Telus via either underground / overhead service. The service to the property line will be the responsibility of the developer.

Natural Gas

Each site will have natural gas at the edge of it, with the supplier being the County of Vermilion River's Utility Company.


Internal Road Structure


The construction will meet the specifications of the County, which can generally be described as a 1m grade with an 8.0-8.5m top. Completion will be a cold roll asphalt surface.


Sewage System

The sewage systems will be in accordance to the guidelines set out by the province. None of the properties is large enough for pump out systems. It is expected that systems will consist of underground fields or a haul out process.

Each acreage owner will be responsible for their own system.







MATRIX PLANNING

Scale - 1:60 000

G.T. Hofmann & Associates


IDP Boundary
Lloydminster City Boundary
Air Photo Date: April 2003 (1:20,000)


EUB History of Pipelines and Wells

The accompanying map prepared the G.T. Hofmann and Associates plots out the Oil/Gas Infrastructure that is part of the Intermunicipal Development Plan between the City of Lloydminster and the County of Vermilion River.

The SW 19 50 R1 W4 indicates the existence of a Low Pressure Pipeline. This line belongs to the County and supplies natural gas to a number of homes in the vicinity.


The history of the property indicates no wells or other pipelines have been located on it.





Farmland Assessment Rating


The map as presented by Matrix Planning indicates the soil has an agricultural rating of Class 2 and 3.



Groundwater Potential Plan

The Groundwater Potential Plan was completed by McAllister Drilling Inc. of Lloydminster, Alberta. A total of 4 wells were tested, which were either on this quarter of land, or in the immediate vicinity.

Attached is a copy of the data collected, and a map of the well locations.



Water Well Test Folic

Date <u>Feb 18/06</u> Time <u>1.306m</u>

Program Nam	<u>.</u> e		Job #
		Modin	Phone #
Address:	Edmont	on Alta	
L.S.D. NW	Sec. 19	Twp. 49 I	Rge W. of _ 4
Description of	f Well location	on property,	10 meters
-	of shop.	=,	
	eun m'Allister		463AD. Phone #8081597
			casing
Well depth	-	Pump_	Submersible
Static level	28.715	Pumpin,	g Rate <u>4.15 qpm</u>
Water sample		÷	
Age of well	Type	of Well Dr	illed.
Pre test F	ost test	Analysis r	equired: Yes _ No _
·	Domestic / Li		•
	or the contract of the contrac		
Pumping	[Vāimutes]	Recovery	Comments:
		\$	200 gpd.
			agreement of the control of the cont
	was fair to the fair and the original and the control of the contr	i yana iki ingangi ingangangangangangangangangangan kananan ya pangangangan kananan kananan amanan angan angan	CPS
<u> </u>	AND AND THE PROPERTY OF THE CONTRACT OF THE CO	antigangga mati dan di Salaman San Caman bandan banan sayan sayan sayan sayan sayan sayan sayan sayan sayan sa	N 534 14.563'
The graph of the process of the contract of th			ω 110th 08.971'
· · · · · · · · · · · · · · · · · · ·		والمستعدد والمرابع والمستعدد والمستعد والمستعدد والمستعد والمستعدد والمستعد والمستعدد	
androly androld agricultures of Kinglyberg Adapting his baken proges (Kinglyberg). P		The same of the sa	#]
The state of the s			i promonenti.
		والمستقد والمستقد والمستون والمدارية والمستقد والمستقد والمستقد والمستقد والمستقد والمستقد والمستقد	
	A STORES AND	and the state of t	anti-Alfred
	The second secon	المعادلة والمعادلة والمعادلة والمعادلة المستحدة والمعادلة والمعادلة والمعادلة والمعادلة والمعادلة والمعادلة وا	
		Standard and professional programme and an analysis of the second professional professional and the second profess	
والمراجعة المراجعة ال	والمرابعة والمرا	والمستران	
والمراجعة والمستحدة المراجعة والمراجعة والمراج	The second secon		
	The state of the s	مياهم والمهار جهيم والمهاجون المساوحة فسناه كالأمام المساوي ويهار والمهار والمهام الملاسية	19.75.77.77.77.77.77.77.77.77.77.77.77.77.

Water Well Test Forth

Date <u>Feb 18/06</u> Time 1.00 Pm

Program Name	Job #
	nitchell Phone#
Address: Red De	
L.S.D. SF Sec.)4	Twp. <u>ug</u> Rge. 2 W. of <u>4</u>
Description of Well location	n on property, In pumphouse
30 meters north	& lometers east of house
Well Tester Dean in Allister	Lic. #3463A Phone #8081597
Measurements taken from	Top of well pit board cover
Well depth	Pump Submersible
Static level 33.66	Pump <u>Submersible</u> Pumping Rate <u>5 qpm</u>
Water sample taken from	
Age of well old. Type	of Well <u>6" steel casing</u> Analysis required: Yes No
Pre test Post test	Analysis required: Yes No
Well Use: Domestic 🗸 L	_ivestock
Pumping Minutes	Recovery Comments:
	COCO
	GPS Reading
	N 53# 14.341
	W 110 H 09.128
	3-0-4
	usage - 300 qpd.
	Add to an add the state of the
	N. 25 a. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1.
	Section of the sectio
	THE PART OF THE PA
	The state of the s
	California Printer Printer California (California California Calif

Water Well Test Folto

Date <u>Feb 18/06</u> Time <u>2.15 Pm</u>.

Program Name	Job #
Land owner name ola Heggeth Pho	me# 8758699
Address: BR5 Lloud Alfa	
Address: RR5 Lloyd Alta L.S.D. Nw Sec. 19 Twp. 49 Rgc. 1	W. of 4
Description of Well location on property, 25	meters
horth of house	
Well Tester Dean in Allister Lic. #	Phone #
Measurements taken from Top of Casing	
Well depth 260 Pump Sub	mersible
Measurements taken from Top of casing Well depth 260 Pump Sub Static level 29.28 Pumping Rate	2 apm
Water sample taken from	
Age of well 1996 Type of Well Drilled 5	"plastic
Pre test Post test Analysis required:	Yes No
Well Use: Domestic Livestock	
Pumping Minutes Recovery Con	ements:
350	gpd.
	- 4 4 0 0 0 0 1
A STATE OF THE PROPERTY OF THE	34 14.755'
- W 111	08.976'
The state of the s	
The second of th	
And Prince and the Control of the Co	
The second secon	
The second secon	
The state of the s	
The state of the s	

Water Well Test Folds

Date Fe 52 7/06
Time 5.00 Pm

Program Name	Job #
Land owner name Norm Dallyn	Phone # 8150362.
Address: Box 367 Lloyd, Sast	K. 59VDYY.
L.S.D. S. Sec. 19 Twp. 49 1	
Description of Well location on property,	
N.W. of Louse.	
Well Tester Lic. #	Phone #
Measurements taken from Top of	casing
Measurements taken from Top of a Well depth 240ft. Pump	submersible
Static level 320/ Pumpin	g Rate 8gpm.
Water sample taken from	
Age of well Type of Well De-	illed 5"plastic
Age of well Type of Well Pre test Post test Analysis re	equired: Yes No
Well Use: Domestic / Livestock	*
Pumping Minutes Recovery	Comments:
	-
10 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	Well usage 600gpm
	the property of the state of th
The state of the s	W53 4 14.098'
	} ·
	W 110 # 08.972'
	,

Natural Features

The topography of the site can be described as rolling with natural drainage from the S.W. corner, which is the highest point to the East and North into Devonia Lake.


The Development offers a variety of possibilities for home construction:

- 1) Lake Front
- 2) Hillside Plans
- 3) View Lots with a 40 foot rise above the Lake
- 4) Walkout designs

There should be no water problems due to existing natural drainage, the Lake level control system and no drainage over neighbor's properties. The proposed road/ditch infrastructure system follows the natural valleys of the property, collecting run-off from homes built into/on the surrounding hills and delivers it to the lake via 2 low points in the development. Additionally, the banks of the Lake front lots rise rapidly from the water's edge, preventing back flooding should a rising water level occur.

Devonia Lake should be an asset to the Development:

- 1) In 10 years, it has shown no signs of alkalinity, even when there was limited inflow due to drought
- 2) Large numbers of geese and ducks have been observed using it as a home and resting place.



Adjacent Land Uses

North and North East

NW 19 49 R1 W4, E ½ 19 49 R1 W4

- 1) 2 acreages are located along RR20 on the North East Boundary
- Additional properties are crop, hay or pasture. These land parcels are separated from the acreage subdivision by the natural barrier being Devonia Lake.

East

PT SE 19 49 R1 W4

- 1) Located on the East boundary is an approximately 17 acre piece of land. It has been separated from the rest of the quarter by Devonia Lake.
- 2) It is currently in hay production, but could be grazed due to a fence that is on the East boundary.

South and South East


PT SE 18 49 R1 W4, SW 18 49 R1 W4

- 1) These properties are currently used for hay or grazing applications.
- 2) A fence is currently in place on the South Boundary.

West


E ½ 24 49 R2 W4, NE 13 49 R2 W4

 Various agricultural usages have been observed: crops, green feed, swath grazing, and silaging.



Fire Protection


Fire fighting services are available from the volunteer Fire Department located in Blackfoot. The map labelled "Protective Services Fire Districts" indicates which zone this multi-parcel County Residential Subdivision falls in.



School District

The following information was supplied by the Buffalo Trail Public School Division. This Development falls in the Kitscoty Public School System and it is expected that the majority of children would be bussed to that location.

Arrangements can also be made to access the Lloydminster School System.



LLOYDMINSTER TRANSPORTATION SERVICE AREA

Commencing at the Saskatchewan border (Highway #17) at the southeast corner of SE 24-48-1 W4, then five and a half (5 ½) miles west to the southwest corner of SE 19-48-1 W4, then north eighteen (18) miles to the northwest corner of NE 18-51-1 W4, then east five (5) miles to the northwest corner of NE 13-51-1 W4, then four and a half (4 ½) miles north to the northwest corner of SE 12-52-1 W4, then a half (½) mile east to the Saskatchewan border (Highway #17), then south twenty-two and a half (22 ½) miles to the point of commencement, excluding the City of Lloydminster.

^{*}Parents wishing to enroll their children in a school outside of their designated transportation service area may be permitted to do so subject to existing Board Policy EEB4, Boundary Exemption Resident Students.

LLOYDMINSTER BUSES

BUS#	Picks up L.P.S.D. Students attending these schools	Picks up L.C.S.D. Students attending these schools
VR-L1	Jack Kemp Elementary School	St. Mary Elementary School
	E.S. Laird Middle School	Ecole St. Thomas
	Lloydminster Comprehensive H.S.	Holy Rosary High School
VR-L2	Queen Elizabeth Elementary School	St. Mary Elementary School
	E.S. Laird Middle School	Ecole St. Thomas
	Lloydminster Comprehensive H.S.	Holy Rosary High School
VR-L3	Jack Kemp Elementary School	St. Mary Elementary School
	E.S. Laird Middle School	Ecole St. Thomas
	Lloydminster Comprehensive H.S.	Holy Rosary High School
VR-L7	Queen Elizabeth Elementary School	St. Mary Elementary School
	E.S. Laird Middle School	Ecole St. Thomas
	Lloydminster Comprehensive H.S.	Holy Rosary High School

Under the agreement with Lloydminster Public School Division:

Students North of Highway #16 attend Queen Elizabeth Elementary School Students South of Highway #16 attend Jack Kemp Elementary School

We transport to these schools only.

PHASE I ENVIRONMENTAL SITE ASSESSMENT VACANT UNDEVELOPED PROPERTY PORTION OF SW ¼, SEC. 19, TWP. 49, RGE. 1, W4M COUNTY OF VERMILION RIVER, ALBERTA

Submitted to:

2 PGL HOLDINGS PO BOX 96 Blackfoot, Alberta T0B 0L0

Submitted by:

AMEC Earth & Environmental, a division of AMEC Americas Limited 5406 - 52 Avenue Lloydminster, Alberta T9V 2T5

23 February 2006

Project No. AX4762

::__

23 February 2006 Project No. AX4762

2 PGL Holdings PO Box 96 Blackfoot, Alberta T0B 0L0

Attention:

Mr. Lorie Peregrym

Dear Sir:

RE:

Phase I Environmental Site Assessment

Vacant Undeveloped Property

Portion of SW 1/4, Sec.19, Twp. 49, Rge. 1, W4M

County of Vermilion River, Alberta

AMEC Earth & Environmental (AMEC) is pleased to provide two bound copies of the above noted report. Based on information made available to AMEC through a historical records search and review, a site visit, and interviews with people familiar with the Site no environmental issues were identified.

I trust this meets your present requirements. If you have any questions, concerns or require further clarification regarding the contents of the report, please do not hesitate to contact this office.

Respectfully Submitted,

AMEC Earth & Environmental, a division of AMEC Americas Limited

Tammy Sahaydak

Environmental Technician

Lloydminster, Alberta

TNS/jbb

Paul Larsen, C.E.T., C.E.S.A. Manager of Technical Services Lloydminster/Bonnyville, Alberta

P:\Geotechnical\AX4700 - AX4799\AX4762\AX4762 Final Report.doc

AMEC Earth & Environmental, a division of AMEC Americas Limited 5406 – 52 Avenue Lloydminster, Alberta Canada T9V 2T5 Tel +1 (780) 875-8975 Fax +1 (780) 875-1970

EXECUTIVE SUMMARY

PROJECT NAME: Phase I Environmental Site Assessment

CIVIC ADDRESS: Not Applicable

LEGAL DESCRIPTION: SW 1/4, Sec. 19, Twp. 49, Rge. 1, W4M

County of Vermilion River, Alberta

SITE OWNER: Lorie Derwayne Peregrym and Glenda Noreen Peregrym

OCCUPANCY: Vacant Undeveloped property

SITE DESCRIPTION: The Site is located 10 km west and 5 km south of Lloydminster,

Alberta and is located within SW ¼, Sec.19, Twp. 49, Rge. 1, W4M The Site, having an area of 48.2 hectares, consists of undulating terrain and generally slopes northeast toward Devonia Lake which encroaches from the northeast. A tree line borders the west site boundary and bush and trees follow the contour of the lake on the northeast boundary of the Site. The Site is currently utilized as

agricultural cropland.

ADJACENT LAND USE: Agricultural property containing scattered oilfield leases are

located to the north, east, south, and west of the Site. Farmyards are also located on the adjacent properties at the northwest and

southwest comers of the site.

FINDINGS: Based on information made available to AMEC through a historical

records search and review, a site visit, and interviews with people familiar with the Site, no environmental issues were identified.

TABLE OF CONTENTS

Execu		mmarytents	
		Page	∍ No
1.0	INTRO 1.1 1.2	DDUCTIONPROJECT BACKGROUNDSITE LOCATION	1
2.0	METH 2.1 2.2 2.3 2.4 2.5	ODS OBJECTIVE SCOPE HISTORICAL RECORDS SEARCH ENVIRONMENTAL REGISTRATIONS SITE VISIT	1 1 2
3.0	RESUL 3.1	HISTORICAL LAND USE 3.1.1 Historical Aerial Photographic Information 3.1.2 Land Titles Information 3.1.3 Municipal Records Review 3.1.4 Interviews ENVIRONMENTAL REGISTRATIONS	3 4 4
	3.3 3.4	SITE VISIT SITE CONDITIONS 3.4.1 Site Description 3.4.2 Site Drainage and Topography 3.4.3 Regional Geology and Hydrogeology 3.4.4 Adjacent Properties	6 6 6
4.0	SITE (4.1 4.2 4.3 4.4 4.5 4.6 4.7 4.8 4.9	OBSERVATIONS ASBESTOS CONTAINING MATERIALS (ACMs)	7 7 7 7 8
	T.U	STORAGE AND DISPOSAL	8

TABLE OF CONTENTS (continued)

	4.10	SUMPS AND DRAINS	8
	4.11	AIR EMISSIONS	8
	4.12	WATER EMISSIONS	8
	4.13	DUMPS AND LANDFILL	8
	4.14	RADON AND METHANE GAS	9
	4.15	HERBICIDES AND PESTICIDES	9
	4.16	NUISANCE ODOURS AND NOISE	9
	4.17	ADDITIONAL OBSERVATIONS	9
5.0	CON	CERNS AND RECOMMENDATIONS	9
6.0	CLOS	BURE	9

LIST OF FIGURES

FIGURE 1: Plan Showing Location of the Site (SW 1/4, Sec. 19, Twp. 49, Rge. 1, W4M)

APPENDICES

APPENDIX A: Completed Checklists

APPENDIX B: Historical Aerial Photographs and Site Photographs

APPENDIX C: Land Titles Information

APPENDIX D: Correspondence

APPENDIX E: Standard Terms and Conditions

...

Glossary of Commonly Used Abbreviations

ACM Asbestos Containing Material

AMEC Earth & Environmental, a division of AMEC Americas Limited

AST Aboveground Storage Tank

AENV Alberta Environment
ELC Environmental Law Centre

EPEA Environmental Protection and Enhancement Act

ESA Environmental Site Assessment

FOIP Freedom of Information and Protection of Privacy

H.E.L.P. Help End Landfill Pollution Insurer's Advisory Organization

LBP Lead Based Paint

MSDS Material Safety Data Sheet

NORM Naturally Occurring Radioactive Material

ODS Ozone Depleting Substances
PCB Polychlorinated Biphenyl

PTMAA Petroleum Tank Management Association of Alberta

SE Saskatchewan Environment

UFFI Urea Formaldehyde Foam Insulation

UST Underground Storage Tank

WHMIS Workplace Hazardous Materials Information System

AX4762 Final Report.doc Page iv

1.0 INTRODUCTION

This report presents the results of a Phase I Environmental Site Assessment (ESA) for a vacant undeveloped property (SW ¼, Sec.19, Twp. 49, Rge. 1, W4M) southwest of Lloydminster, Alberta; hereafter referred to as the 'Site'.

1.1 PROJECT BACKGROUND

Mr. Lorie Peregrym of 2 PGL Holdings retained AMEC Earth & Environmental (AMEC) to conduct a Phase I ESA for the above referenced property. Authorization to conduct the environmental investigation was received from Mr. Lorie Peregrym of 2 PGL Holdings on 30 January 2006.

1.2 SITE LOCATION

The Site is located 10 km west and 5 km south of Lloydminster, Alberta within SW ¼, Sec.19, Twp. 49, Rge. 1, W4M. The Site is bordered by Devonia Lake to the northeast and by Range Road 20 to the west. Agricultural property with scattered oilfield leases borders the Site to the north, east, south, and west. Farmyards are also located adjacent the southwest corner of the Site, and on the adjacent north and west properties. The Site location is shown on Figure 1.

2.0 METHODS

2.1 OBJECTIVE

The objective of this Phase I ESA is to identify actual or potential environmental contamination that could be associated with current and past activities on the Site, and to determine if additional investigations are recommended.

2.2 SCOPE

AMEC's methodology in conducting Phase I ESAs is based on the requirements in the Canadian Standards Association¹ guidelines. A standardized checklist was used as a guide during the inspection and is presented in Appendix A.

The Phase I ESA consisted of:

- a historic records search and review to identify any conditions, practices and operations, current or past, which may constitute an environmental concern to the Site;
- correspondence with the provincial or municipal environmental regulatory agencies to determine environmental requirements and registrations for the Site;

^{1.} Canadian Standards Association (CSA). (2001). Phase I Environmental Site Assessment (CSA Z768.01). Ottawa, Canada.

- a site visit to identify conditions or practices that may represent an environmental concern;
- interviews with persons knowledgeable about the Site; and
- the preparation of a report summarizing the methodology and findings of the historical and site reconnaissance tasks. This report would include recommendations for additional detailed investigation and assessment, if necessary.

Physical sampling and analysis of soils and/or groundwater are beyond the scope of this Phase I ESA. Those portions of the SW ¼, Sec. 19, Twp. 49, Rge. 1, W4M currently covered by the water of Devonia Lake and the farmyard to the southwest corner of the Site are beyond the scope of this Phase I ESA.

2.3 HISTORICAL RECORDS SEARCH

A historical records search was conducted to develop a profile of the Site and adjacent properties' history. Information sources included:

- aerial photographs;
- land titles information;
- review of municipal files and plans; and
- persons familiar with the Site and area history.

Historical aerial photographs were obtained from AMEC's in-house library. Historical aerial photographs are useful for identifying land uses, structures and development.

A request for a historical land titles search was made to Wilson Registries in Lloydminster, Alberta. The purpose of the land titles search was to determine previous ownership of the Site.

A request to review files and plans for the Site was made to Mr. Randy Belliveau of the County of Vermilion River.

Other persons familiar with area history were interviewed to obtain information pertaining to the Site and adjacent properties.

2.4 ENVIRONMENTAL REGISTRATIONS

A request for a well site reclamation historical search of the SW ¼, Sec. 19, Twp. 49, Rge. 1, W4M made to the Environmental Law Centre. File searches include information supplied by Alberta Environment (AENV) with respect to Reclamation Certificates (applied for, issued or cancelled), Environmental Protection Orders, and Conservation and Reclamation Orders, Enforcement Orders, Reclamation Orders, and Conservation and Reclamation Notices issued pursuant to the Alberta Environmental Protection and Enhancement Act (EPEA) and its

: _

predecessor legislation, the "Land Surface Conservation Act" and the "Surface Reclamation Act" since 1963.

A review of Alberta Environment's Help End Landfill Pollution (H.E.L.P.) project registry of industrial landfill sites and other published data was undertaken to identify any registered landfills that may have been present in the immediate area of the Site.

A request for records of active tank sites and inventory of abandoned tank sites for the Site was made to the Petroleum Tank Management Association of Alberta (PTMAA).

A request for a file search of the Site was made to Alberta Transportation's Dangerous Goods Control to provide information on any reported dangerous goods incidents that may have occurred at or near the Site.

AENV's Freedom of Information and Protection of Privacy (FOIP) office was contacted to inquire about the availability of readily available scientific and technical reports documenting contamination, records of spills or releases, investigations, activities and enforcement actions that are related to the Site.

The Abacus Diagnostic Report was reviewed for the section the Site is in and the adjacent sections.

2.5 SITE VISIT

A site visit was undertaken during which the Site and adjacent properties were visually inspected. The purpose of the site visit was to identify conditions or practices which may represent an environmental concern. In addition, the site visit was used to confirm and to expand upon findings of the historical records search and review.

3.0 RESULTS AND DISCUSSION

3.1 HISTORICAL LAND USE

3.1.1 Historical Aerial Photographic Information

Reproductions of historical aerial photographs for the Site and the surrounding area were obtained for the years 1949, 1965, 1975, 1982, 1991 and 2001. The features observed in the photographs are summarized below.

The Site appeared to consist of cleared agricultural property as well as undeveloped bush and trees. Range Road 20 was established and was evident along the west Site boundary. Devonia Lake formed the northeast boundary of the Site. Adjacent properties to the south and west beyond Range Road 20 appeared to consist of agricultural property.

- 1965 The Site and the adjacent properties appeared similar to the 1949 aerial photograph.
- 1975 The Site and adjacent properties appeared similar to the 1965 aerial photograph.
- 1982 The entire Site appeared to consist of cleared agricultural property. The adjacent properties appeared similar to the 1975 aerial photograph.
- The Site and the adjacent properties appeared similar to the 1982 aerial photograph except for a farmyard (120 m x150 m) evident adjacent to the southwest comer of the Site, and a farmyard evident on the adjacent property to the north at the northwest comer of the Site.
- 2001 The Site and the adjacent properties appeared similar to the 1991 aerial photograph.

No potential environmental concerns were identified by the historical aerial photograph review.

Copies of historical aerial photographs appear in Appendix B.

3.1.2 Land Titles Information

A summary of available Land Titles information is as follows:

SW 1/4, Sec. 19, Twp. 49, Rge. 1, W4M

- 1996 Lorie Derwayne Peregrym and Glenda Noreen Peregrym
- 1996 Charles Ernest Brown and Janet Kathleen Brown

A copy of the most recent Certificate of Title for the Site is provided in Appendix C.

3.1.3 Municipal Records Review

A response from Mr. Randy Belliveau of the County of Vermilion River revealed that only a blank file for the Site exists as it has never been developed.

3.1.4 Interviews

Mr. Randy Belliveau of the County of Vermilion River indicated that the Site consists of agricultural land. It was understood that the Site has only been used as agricultural crop and pasture land. Mr. Belliveau was not aware of any environmental concerns.

AX4762 Final Report.doc Page 4

Mr. Lorie Peregrym of 2 PGL Holdings, owner of the Site from 1996 to 2006, indicated that no reclamation has been undertaken and that no gas/oil wells have been present on Site. In October 2000, Husky Energy had completed 2-D seismic on the land. In the fall of 2005, 3-D seismic was completed on the adjacent land to the west across range road 20. Mr. Peregrym also indicated that to the best of his knowledge no USTs or ASTs are located in the farmyard adjacent to the southwest comer of the Site. It was also understood that no underground utilities exist on Site except for two underground natural gas lines that service the three farm yards on the adjacent properties.

3.2 ENVIRONMENTAL REGISTRATIONS

A formal response from the ELC indicated that as of 2 February 2006, with respect to SW ¼, Sec. 19, Twp. 49, Rge.1, W4M no Reclamation Certificates (applied for, issued or cancelled), Reclamation Orders and Conservation and Reclamation Notices were issued pursuant to the "Alberta Environmental Protection and Enhancement Act" and its predecessor legislation, the "Land Surface Conservation and Reclamation Act" and the "Surface Reclamation Act" since 1963.

No landfill sites were recorded within the SW ¼, Sec. 19, Twp. 49, Rge.1, W4M or on the adjacent properties according to Alberta Environment's H.E.L.P. (Help End Landfill Pollution) program².

A formal response from PTMAA indicated that there are no records of active tank sites or abandoned tank sites at the Site.

A formal response from Alberta Transportation's Dangerous Goods Control indicated that they are not capable of searching by LSD. Dangerous Goods spills are recorded by highway number and location or by street, address, and municipality.

A formal response from the AENV FOIP office indicated that Alberta Environment has not found any routinely available records under the Environmental Protection and Enhancement (EPEA) Legislation.

A review of the Abacus Diagnostic Report identified the following:

- Oil and Gas Well Summary
 - No oil and/or gas well leases in the target quarter section.
 - Three oil and gas well leases (one active, two abandoned) in the quarter section adjacent to the south; the closest at a distance of approximately 350 m.
 - Five oil and/or gas well leases (three active, two abandoned) in the quarter section to the west; the closest at a distance of approximately 325 m.

² Alberta Environment, 1988. Data Tracking and Management Control System H.E.L.P. (Help End Landfill Pollution) Program, Industrial Waste Landfill Program, Edmonton, Alberta.

3.3 SITE VISIT

A site visit was conducted by an AMEC representative. The Site and adjacent properties were visually inspected to identify evidence of contamination in the form of soil disturbance, waste storage/spillage, and staining or discoloration of soils. An inspection of the Site was also carried out to determine the presence of hazardous materials or other chemicals or wastes as applicable. AMEC's own in-house standardized site inspection checklist was used and is presented in Appendix A.

3.4 SITE CONDITIONS

3.4.1 Site Description

The Site consists of undulating terrain and generally slopes toward the northeast toward Devonia Lake on the northeast portion of the Site. A tree line borders the west Site boundary and bush follows the contour of Devonia Lake on the northeast quarter of the Site. The Site is agricultural property. A low pressure gas line is also located on the west boundary of the Site.

3.4.2 Site Drainage and Topography

The ground surface across the Site consists of undulating terrain. Scattered low lying areas across the Site are likely poorly drained or undrained. Generally surface runoff water would likely move northeast across the Site toward Devonia Lake.

3.4.3 Regional Geology and Hydrogeology

The bedrock underlying the Blackfoot area is the Belly River Formation³ that consists of non marine thick-bedded feldspathic sandstone, clayey siltstone, and mudstone which are grey to greyish green in color, and contain concretionary ironstone beds. Drift thickness is estimated between 50 m and 150 m in depth. The subsurface soils in the vicinity of the Site generally consist of a glacial till deposit. The till (an unsorted mixture of earth materials deposited directly from the glacier) is generally low to medium plastic soil containing sand, silt and clay. Scattered sand and gravel deposits frequently break the till and are considered a major source of groundwater. Groundwater flow in the vicinity of the Site is anticipated to be towards the northeast.

AX4762 Final Report.doc

^{1976;} Hydrogeology of the Vermilion Area, Alberta, Report 75-5, Alberta Research Council.

3.4.4 Adjacent Properties

The adjacent properties consist of agricultural property and Devonia Lake to the northeast as follows:

- North Agricultural property with a farmyard. Storage of a few old vehicles and farm machinery.
- South Agricultural property. Farmyard adjacent to the southwest corner of the Site includes a house, sheds, bam, shop and garage. A former oil/gas well lease was located approximately 350 m south of the Site.
- East Agricultural property.
- West Agricultural property and a farmyard to the west beyond Range Road 20. A former oil/gas well lease was located approximately 325 m west of the Site.

4.0 SITE OBSERVATIONS

The site observations are presented in the following text and the completed checklists are included in Appendix A. The inspection was limited to areas readily accessible.

4.1 ASBESTOS CONTAINING MATERIALS (ACMs)

No potential ACMs were observed at the Site.

4.2 UREA FORMALDEHYDE FOAM INSULATION (UFFI)

No evidence of UFFI was observed at the Site.

4.3 LEAD-BASED PAINTS (LBP)

No potential sources of lead were observed at the Site.

4.4 POLYCHLORINATED BIPHENYLS (PCBs)

No potential PCB-containing electrical equipment was observed at the Site.

4.5 OZONE DEPLETING SUBSTANCES (ODSs)

No potential ODSs were observed at the Site.

4.6 CHEMICAL INVENTORY, STORAGE AND HANDLING

No chemicals were observed at the Site.

4.7 STORAGE TANKS

Aboveground Storage Tanks (ASTs)

No ASTs were observed at the Site.

Underground Storage Tanks (USTs)

No USTs were observed at the Site.

4.8 HAZARDOUS MATERIAL AND EQUIPMENT

No hazardous material or equipment was observed at the Site.

4.9 NON HAZARDOUS AND HAZARDOUS WASTE GENERATION, STORAGE AND DISPOSAL

The Site is agricultural cropland, therefore, there is no formal waste disposal. No waste or debris was observed on the Site

4.10 SUMPS

No sumps were identified at the Site.

4.11 AIR EMISSIONS

No air emission sources were identified at the Site.

4.12 WATER EMISSIONS

Stormwater runoff from the Site would likely discharge northeast to the surrounding environment, or be contained within Devonia Lake.

4.13 DUMPS AND LANDFILLS

The Site was agricultural cropland. It was understood that there have not been any quarries, landfills or dumps on the Site or on the adjacent properties. No landfill sites were recorded within the SW ¼, Sec. 19, Twp. 49, Rge. 1, W4M or on the adjacent properties according to Alberta Environment's H.E.L.P. program.

4.14 RADON AND METHANE GAS

It is understood that a radon survey has not been conducted at the Site. Due to alea geology radon is not considered to be of concern. The Site is not in close proximity to a known landfill site. Therefore, methane gas is not considered to be of concern at the Site.

4.15 HERBICIDES AND PESTICIDES

No herbicides and pesticides were understood to have been used at the Site.

4.16 NUISANCE ODOURS AND NOISE

No nuisance odours or noise were observed at the Site.

4.17 ADDITIONAL OBSERVATIONS

There are farmyards adjacent to the northwest and southwest comers of the Site, as well as beyond Range Road 20 to the west. Oil and/or gas well leases (current and past) were identified on the adjacent properties to the south and the west beyond Range Road 20. The closest oilfield lease to the south was of a distance of approximately 350 m. This well site was abandoned in 1957. The closest oilfield lease to the west was at a distance of approximately 325 m and was abandoned in 1957. No other additional observations were noted.

5.0 CONCERNS AND RECOMMENDATIONS

Based on information made available to AMEC through a historical records search and review, a site visit, and interviews with people familiar with the Site, no environmental issues were identified:

6.0 CLOSURE

This assessment has been conducted using generally accepted environmental practices based on visual observations and historical data review. Performance of a standardized environmental site assessment protocol is intended to reduce, but not eliminate, uncertainty regarding the potential for recognized environment conditions in connection with the Site given reasonable limits of time and cost.

This report has been prepared for the exclusive use of 2 PGL Holdings and authorized users for specific application to this project site. The report may be relied upon for mortgage financing purposes. The environmental investigation was conducted in accordance with the proposed work scope prepared for this Site, verbal and written requests from Mr. Lorie Peregrym, and generally accepted assessment practices. No other warranty, expressed or implied, is made. The standard terms and conditions of this report are specified in Appendix E.

AMEC does not accept any responsibility for the use of this report, in whole or in part, for any purpose other than that intended or to any third party for any use whatsoever. AMEC requires that third parties wishing to rely on this report firstly agree to be bound by our proposal and AMEC's standard reliance letter. Provided that the report is still reliable, and less than 12 months old, AMEC will issue a third party reliance letter to third parties that the client has identified in writing, upon payment of current reliance letter fees. AMEC's standard reliance letter indicates that in no event shall AMEC be liable for any damages whatsoever, relating to third party reliance on AMEC's report. No reliance by any third party is permitted without such agreement.

Respectfully submitted,

AMEC Earth & Environmental, a division of AMEC Americas Limited

Tammy Sahaydak Environmental Technician


Lloydminster, Alberta

Reviewed by:

Silvan Zorzut Senior Environmental Site Assessor

TNS/jbb

Paul Larsen, C.E.T., C.E.S.A. Manager of Technical Services Lloydminster/Bonnyville, Alberta



SITE PLAN SHOWING LOCATION OF SITE (SW - 19 - 49 - 1 - W4M)



2PGL HOLDINGS
PHASE I ENVIRONMENTAL SITE ASSESSMENT
SW - 19 - 49 - 1 - W4M
LLOYDMINSTER, ALBERTA

Made: PEL Checked: PEL Scale: 1: 40000 Project No.: AX4762 Figure: 1

APPENDIX A

COMPLETED CHECKLISTS

General Site Information

INITIAL ENVIRONMENTAL ASSESSMENT CHECKLIST

Undeveloped Land or Site

Date	: 15 Fe	bruary 2	006	_ Jok	o No.	AX476Z
Prep			Laydak			
Lot		Block	_ Plan			
Muni	cipality/Town:	ship/County	SW.19-49-	1-u	14M	
Addr	ess _					
	-					
	_			. 		
	ohone		Contact	:		
Size	of Property	48.2 hect	arus S Any Struc	ctures	s on Prop	ertv?
			(If Yes, pi		•	uilding Form)
			yout and Occupanc	_	_	
<u> </u>	agricultu	iral. Crop	land		***************************************	
						
				·		
						
1.	SITE DESCI	RIPTION:				
A)	Topography		Flat Land			Dry Land
			Hilly Terrain			Swampy Land
			High Elevation			Sloped
			Low Elevation		along Last File	Other (depressions)
			rolling (undularly			Unknown

B)	Soil Profile		Rocks				berry .	Top Soil
			Sand					Silt
			Clay					Other
								Unknown
C)	Are any of the fol property?	lowing water	sources	on the	prope	rty or do t	hey pa	ss through the
	N	lone					Strea	ams
	L	akes		سا			Char	nnels/Ditches
	R	ivers					unkn	own
D)	Are there any of t	he following	features o	on the s	site? (Yes or No	D)	
	M	lounds (Rochs)	~		······································	Pond	ls
	P	its					Lago	ons
5)	i) Is there any ev ii) If yes, please i			<u></u>	1			
F)	Is the property loc	cated near a	ny ecologi	cally se	ensitiv	e areas?	Yes o	or No
	If Yes, please chec	ck type of are	ea and ap _l	oroxim	ate dis	stance to:		
		Wetlands	•					Other
		Flood Pla	ain			· · ·		Unknown
		Coastal 2	Сопе					

7.	Perimeter Property Usage:	farmine	-agricultural
	croplan		
Н.	Prior Owner of Property:	arlo Errest	Brown & Janet
	kathlen	Brown	

. Prior Use(s) of Property:	
Commercial	Mining
Residential	Industrial
Farm Land	Undeveloped
Forest	Unknown
Other	

J. Proximity to Known Contamination Sites:

II ENVIRONMENTAL CONCERNS

A. Are they property?	any <u>obvious physical</u> signs of contamination on or around the
	None
	Drums or Containers (Buried or Above Ground)
	Stained Soil
	Vegetation Damage
	Foul or Unusual Odours
	Oily Sheen or Discoloration or Surface Water
	Evidence of Dumping
	Other

			Yes	No	Unknown
B.	Ar	e there any groundwater wells on the property?			
C.	ls	the depth to groundwater known?			
D.		the groundwater in the immediate area used a source of drinking water?			
E.		the surface water on the property, or passing through e property, used as a source of drinking water?			~
F.	on	the property, or any of the adjacent properties, a federal, state, provincial or local list of zardous waste sites?			
G.		the property the subject of environmental gation or regulatory enforcement action?			
Н.		e there any adverse press reports or complaints file concerning the property?			
l. —		the property designated as a flood plain, wetland, sensitive ecological area?		V	
J.	rai	e there any easements on the property (roadways, ilways, pipelines, etc) with potential environmental plication?		/	
K.	i	Have any soil samples been analyzed for any contaminants?			
	ii	Have the test results indicated contamination?		NA	
L.	i	Has the water quality been tested on the supply to the property? (streams, rivers, etc.)			
	ii	Have the results indicated contamination?			
Μ.	i	Has the water quality been tested on the discharge from the property?			
*******	ii	Have the results indicated contamination?			
N.	Ple	ease use this area if description of any issue is required.			
	-				

Note: Go to the Master Checklist and Topic Specific Checklists is further detailed descriptions are required or warranted.

:::

ASSESSMENT INFORMATION REQUEST FORM

Legal Address: SW-1949-1-W4M
Municipal Address:
current Owner: Lorie Peregrym et Glenda Peregrym
Are/were there any underground or aboveground storage tanks (USTs/ASTs) at this site?
YesNo
a) If yes, how many USTs/ASTs/ are/were there and what are/were their contents?
b) Where are/were these USTs/ASTs located?
c) If the USTs/ASTs are no longer present, when were they removed?
2. Have there been any hydraulic lifts, hoists or dock levelers been noted on this property? Yes No
Has the owner or agent ever appealed their assessment because of environmental concerns? Yes No Details of concern:
4. When was the building(s) or various additions built?


5. List the building types and the construction materials.




6. What is the size of the lot and individual buildings?




7. What is the zoning for the site?





APPENDIX B

HISTORICAL AERIAL PHOTOGRAPHS
AND SITE PHOTOGRAPHS




AERIAL PHOTOGRAPH OF THE SITE AND SURROUNDING PROPERTIES AERIAL PHOTOGRAPH TAKEN IN 1949



2PGL HOLDINGS
PHASE I ENVIRONMENTAL SITE ASSESSMENT
SW - 19 - 49 - 1 - W4M
LLOYDMINSTER, ALBERTA

Made: PEL Checked: PEL Scale: 1: 40000 Project No.: AX4762 Plate: 1



AERIAL PHOTOGRAPH OF THE SITE AND SURROUNDING PROPERTIES
AERIAL PHOTOGRAPH TAKEN IN 1965




2PGL HOLDINGS
PHASE I ENVIRONMENTAL SITE ASSESSMENT
SW - 19 - 49 - 1 - W4M
LLOYDMINSTER, ALBERTA

Made: PEL

Checked: PEL

Scale: 1: 31680

Project No.: AX4762



AERIAL PHOTOGRAPH OF THE SITE AND SURROUNDING PROPERTIES AERIAL PHOTOGRAPH TAKEN IN 1975




2PGL HOLDINGS
PHASE I ENVIRONMENTAL SITE ASSESSMENT
SW - 19 - 49 - 1 - W4M
LLOYDMINSTER, ALBERTA

Made: PEL

Checked: PEL

Scale: 1: 31680

Project No.: AX4762



AERIAL PHOTOGRAPH OF THE SITE AND SURROUNDING PROPERTIES
AERIAL PHOTOGRAPH TAKEN IN 1982




2PGL HOLDINGS
PHASE I ENVIRONMENTAL SITE ASSESSMENT
SW - 19 - 49 - 1 - W4M
LLOYDMINSTER, ALBERTA

Made: PEL Ch

Checked: PEL

Scale: 1: 30000

Project No.: AX4762



AERIAL PHOTOGRAPH OF THE SITE AND SURROUNDING PROPERTIES AERIAL PHOTOGRAPH TAKEN IN 1991



2PGL HOLDINGS
PHASE I ENVIRONMENTAL SITE ASSESSMENT
SW - 19 - 49 - 1 - W4M
LLOYDMINSTER, ALBERTA

Made: PEL Checked: PEL Scale: 1 : 30000 Project No.; AX4762 Plate: 5



AERIAL PHOTOGRAPH OF THE SITE AND SURROUNDING PROPERTIES AERIAL PHOTOGRAPH TAKEN IN 2001




2PGL HOLDINGS
PHASE I ENVIRONMENTAL SITE ASSESSMENT
SW - 19 - 49 - 1 - W4M
LLOYDMINSTER, ALBERTA

Made: PEL

Checked: PEL

Scale: 1: 30000

Project No.: AX4762



PHOTOGRAPH VIEWS WEST FROM THE NORTHEAST CORNER OF THE SITE ALONG DEVONIA LAKE



PHOTOGRAPH VIEWS NORTHEAST FROM THE SOUTHEAST CORNER OF THE SITE



2PGL HOLDINGS
PHASE I ENVIRONMENTAL SITE ASSESSMENT
SW - 19 - 49 - 1 - W4M
LLOYDMINSTER, ALBERTA

Made: TNS Checked: PEL Scale: NTS Project No.: AX4762 Plate: 7

APPENDIX D

CORRESPONDENCE

ENVIRONMENTAL LAW CENTRE

204, 10709 - Jasper Avenue, Edmonton, AB T5J 3N3

Phone: (780) 424-5099 Fax: (780) 424-5133

E-Mail: elc@elc.ab.ca Home Page: http://www.elc.ab.ca

February 2, 2006

Our File: 006831

Mr. Paul Larsen AMEC Earth & Environmental Limited 5406-52 Avenue Lloydminster, AB T9V 2T5

Dear Mr. Larsen:

RE: Search Requested - SW 19-49-1-W4M

In response to your request of January 31, 2006, we have searched the Wellsite Reclamation Historical Search Service database for the following quarter section of land:

W4-01-049-19 SW1/4

and can advise that as of today's date, there have been NO Reclamation Certificates (applied for, issued or cancelled), Reclamation Orders and Conservation and Reclamation Notices issued pursuant to the "Alberta Environmental Protection and Enhancement Act" and its predecessor legislation, the "Land Surface Conservation and Reclamation Act" and the "Surface Reclamation Act" since 1963.

Information offered by the Wellsite Reclamation Historical Search Service is limited to wellsites, oil production sites, pipelines, compressor sites and some sand and gravel operations on Alberta private land, Special Areas Board land constituted under the "Special Areas Act" and Metis Settlements established under the "Metis Settlements Act". Not included are coal or oil sands mines or exploration sites.

These search results are based on information provided by Alberta Environment ("AENV"). AENV advises that they try to provide the best information possible. However, AENV advises that it cannot guarantee that the information provided is complete or accurate and that any person relying on these search results does so at their own risk.

Information about Environmental Protection Orders, Emergency Environment Protection Orders and Enforcement Orders issued under the "Alberta Environmental Protection and Enhancement Act" can be obtained by searching the Environmental Enforcement Historical Search Service database through the Environmental Law Centre.

Yours sincerely,

Iris Djurfors

Wellsite Reclamation Search Service Coordinator

/id Encl.

Narra Gie No.	to.	ত্ত্ব	ภาก	235	- OHH	MER	Hedin Unit	Gwner	Status (A- Active) (I- fractive)	Siza (Acre)	Priority Ranking	Overell Comments	Wasto Typos	Status	From	2	Design & Operation
CDZ41920	D Blackfoot		SE 17	55 50	6 6	4 4	Міприт-Vетверя	Lloydminster (C)	4	2	2	São of old refinory. SV recuised.		=			o fovedigation planned for 1838
	Lloydminsler	18104	۰	01 50	ā	4						(B3-V4L-104).	Ctay fist, concrete, construction debits.	8	1881	۰	Four groundwater or monitoring wests forburd site. Site
	Lloydninster	nster	•	93	6	*						(83-W1-104).	Spray pond studge, slop pit studge,	\$	1883	1933	Four Groundwater maniforing wells arcurd the site. Site
	Lbydminster	TSIET	٥	93	6	*					_	(83-VAL-104).	Waste time.	22	0	۰	fenced. O Sile fencod.
	Lloydmistor	istor	٥	50	ö	*						Consists of small sites, (83 Leaded gatoline lank WL-104) bottoms.	l Leaded gassäne lank bottoms.	×	1040	1971	Extensive Invest. 1971 undertaken by Hueky 1977 SAA FALERY
	Lkydminster	rster	•	01 50	9	4						(85-742-104).	Off-spec. olly material, off- epocial asphalt.	*	0	1983	an hadr, Skie lencod, Extensivo knest, 1983 undertakon by Husky in 1987, Skie fenced,
	Llaydminster	nster	0	50	9	*					-	(83-VIL-104)	Dictitiate tank studge.	*		1683	Extensive Invect. 1933 undertaken by Hushy in 1937. Ste fenced.
	Llaydminster	95	9	5 5	9	*					•	(83-VIL-104).	Spent lime.	¥	0	1983	Extensive invest. 1983 undertaken by Husky in 1997. Site femond.
	Lloydminster	nster	•	8	6	4						(83-W-104).	Oky wastes.	75	0	1981	Extensive invest. 1984 ondertaken by Husky in 1987. Site fenond
	Llaysminster	rister	0	91 20	6	4						(83-WL-104).	Waste pipe, barrels, spilled aspitelt,	ĸ	c	1980	Extendiva invest.
	Lbydminster	neter	a	22	6	4						Former site of Hodlak refinery, (86-WE-006)	Olly material.	æ	٥	1950	Extensive testing conducted in 1087.
	Lloydminster	विद्य	ی	0Z Z0	5	4						Company to supply environmental impact assessment, (86-VM-006)	Oily wastes.	\$	۰	1960	1960 Extensive leading conducted in 1987.
2001 Husky Oil Operations Ltd.	Lloydminster	inster		02 50	6	4						(88-VM-006).	Asphalt wastes, oly lank bottom wastes.	£	۰	1963	Extensive testing conducted in 1037.
	Lloystminster	nater	,	25	9	₹						(85-VA-039).	Asphalt lank bottoms.	3	1030	1972	1972 Extensive testing conducted in 1987.
	Lloydmlaster	hater	ت	22	6	**						(85-VR-GSS).	Apphalt tenk bottoms.	ਲ	٥	0	Extensive testing conducted in 1937.
	Linydminster	rister	•	25	50	4						Company to supply an environmental Impact study. (65-VII008)	Asphaft.	5	0	1960	Extensive testing conducted in 1987.
2005 Notem Epwty Resources Lid.	Lbydminster	restor	-	\$ 8	99	4						Under ERCB juriediction,	Olly stand.	35	0	1970	Site to be reclaimed 1970 upon facility decommissioning.



Petroleum Tank Management Association of Alberta

Suite 980, 10303 Jaisper Avenue Edmonton, Alberta T5J 3N6 PH: (780)425-8265 or 1-866-222-8265 FAX: (780)425-4722

February 1, 2006

Paul Larsen AMEC Earth & Environmental 5406 52 Avenue Lloydminster, AB T9V 2T5

Dear Paul Larsen:

As per your request, the PTMAA has checked the registration of active tank sites and inventory of abandoned tank sites and there are no records for the property with the legal land description:

SW 19-49-1-W4M, Vermilion River

Please note that both databases are not complete. The main limitation of these databases is that they only include information reported through registration or a survey of abandoned sites completed in 1992 and should not be considered as a comprehensive inventory of all past or present storage tank sites. The PTMAA <u>cannot</u> guarantee that tanks do not or have not existed at this location. Information in the databases is based on information supplied by the owner and the PTMAA cannot guarantee its accuracy. Information on storage tanks or on past or present contaminant investigations may be filed with the local Fire Department or Alberta Environment.

Yours truly.

Connie Jacobsen

PTMAA

Fax

30-12-NAL

Τo Company Compliance Officer

Alberta Transportation & Utilities

Dangerous Goods Control

FROM-AB TRANSPORTATION & ENVIRONMENT

Fax Charge no

(780) 427-1044

File no Fax operator

From Direct Tel

Paul Larsen +1(780) 875-8975

Fax Pages +1(780) 875-1970 1 of 1 (inc. this page)

Date Cc

31 January 2006

Subject

SWYY, Sec19, Two 49, Rael, W4M

Please accept this letter as your authorization to initiate an historical search of the above referenced project. We are performing an Environmental Site Assessment of the above referenced property and would like to know if there are any records of spills or environmental incidents that may have occurred on the site or the surrounding area.

Please fax one (1) copy of the results as soon as possible; Attention: Mr. Paul Larsen.

If you have any questions or require clarification on any matter, please do not hesitate to contact this office (Paul Larsen @ (780) 875-8975).

Respectfully submitted,

AMEC Earth & Environmental, a Division of AMEC Americas Limited

Paul Larsen, C.E.T., C.E.S.A. Manager of Technical Services Llovdminster/Bonnyville

Dangerous Goods spills are recorded by highway number and location or by street address and municipality. Our database is not capable of searching LSD, Plan, Lot or Block,

LT, CIC, 31-Jan-2006

P:\AMEC Misc\Forms\Phase 1\FAX Requests\Dangerous Goods Control.doc

AMEC Earth & Environmental Limited 5406 - 52 Avenue Lloydminster, Alberta Canada Y9V 2T5 Tel +1 (780) 875-8975 Fax +1 (780) 875-1870 MMW.BITTEC.COM

This fax message is confidential. If you are not the intended recipient please notify us by telephone as soon as possible and either return the message by post or destroy it. If you are not the intended recipient, any use by you of its contents is prohibited.





Corporate Services FOIP, Records and Information Management Branch

6th Floor, Petroleum Plaza South 9915 – 108 Street Edmonton AB T5K 2G6 Telephone: (780) 427-4429 Fax: (780) 427-9838

Mr. Paul Larsen AMEC Earth & Environmental Ltd. 5406 - 52 Avenue Lloydminster, Alberta T9V 2T5

FAXED FEB 0 9 2006

February 9, 2006

[Fax:] (780)875 - 1970 Your File #: AX4762

Routine Disclosure Request: 0178-RD-06

Dear Mr. Larsen:

Re: Request for Information Routinely Available under the Environmental Protection and Enhancement (EPEA) legislation. Request for Records Pertaining to the property located at SW Sec 19 Twp 49 Rge 1 W4M, Lloydminster, Alberta.

The following is in response to your request dated February 1, 2006 for the subject records.

Alberta Environment has not identified any routinely available records relating to the subject of your request, based on the search parameters you provided to this office. As a result of our findings, your Routine Disclosure request has been closed.

If you have any further questions or concerns, please write or call me at (780) 427 - 2253

Sincerely,

Jerry Kolar, Advisor





Corporate Services FOIP, Records and Information Management Branch

6th Floor, Petroleum Plaza South 9915 - 108 Street Edmonton, AB T5K 2G6

Telephone: (780) 427-4429 Fax: (780) 427-9838

Mr. Paul Larsen AMEC Earth & Environmental Ltd. 5406 - 52 Avenue Lloydminster, Alberta T9V 2T5

FAXED FEB 0 1 2006

[Fax:] (780) 875 - 1970 Your File #: AX4762

February 1, 2006

Routine Disclosure Request: 0178-RD-06

Dear Mr. Larsen:

Re: Request for Information Routinely Available under the Environmental Protection and Enhancement (EPEA) legislation. Request for Records Pertaining to the Property Located at SW Sec 19 Twp 49 Rge 1 W4M, Lloydminster, Alberta.

Our office received your request for the subject records with the \$25.00 fee on February 1, 2006. We will make every effort to process your request within 30 days. If this timeline changes we will contact you. Enclosed is a receipt for the initial fee.

We have initiated the search for the records you requested as follows:

Location:

SW Sec 19-Twp 49-Rge 1 W4M, Lloydminster, Alberta

10 to 15 miles SW of Lloydminster

Names:

Lorie Peregrym, Glenda Peregrym

Time Frame: Historical search

Records: Scientific/technical information which may include reports documenting the nature and extent of soil, ground and surface water contamination; remedial measures taken to clean-up the site or status of the site; and external correspondence between the submitter and the Department of Environment pertaining to the reports.

If this does not accurately reflect your request, please call me as soon as possible so we can amend the search. Once we receive and review the records you will be contacted.


In addition to the initial fee, you may be required to pay fees for services if the total fee for providing you with the records is expected to be greater than \$150.00. If costs are expected to exceed \$150.00 you will receive a fee estimate letter. [Note: the amount of fees charged for locating and retrieving a record, which is calculated at \$6.75 per 1/4 hour, cannot be reduced if this service has already been provided.]

If you have any questions or concerns, please write or call me at (780) 427 - 2253.

Yours truly,

Jerry Kolar, Advisor

Enclosure (receipt)



-2

NW 18-49-01-W4M:

parameters are an amount of ord , or a supplier of the state of the st			
WELL ID:	00 / 11-18-049-0		
LICENCE #:			AUG 10, 2000
WELL NAME:		MINSTER 11-18-49-1	,
WITHIN:	11-18-049-01 W		
LICENCEE:	DEVON ARL CO		
SPUD DATE:	AUGUST 23, 2000	FINAL DRILL DATE:	
STATUS:	CR-OIL ABD	ABANDONED DATE:	JULY 25, 2003
SURFACE:		DOWNHOLE:	
OFFSETS:	S 734.7 E 465	OFFSETS:	S 734.7 E 465
LATITUDE:	53.227763	LATITUDE:	53.227763
LONGITUDE:	110.144666	LONGITUDE:	110.144666
GROUND ELEVATION:	677.2 m	TOTAL DEPTH:	632 m
		of the companies of the companies of the control of	
WELL ID:	<u> </u>	1 W4 / 0	
LICENCE #:		LICENCE DATE:	AUG 19, 1999
WELL NAME:	ARL 12B LLOYD	12-18-49-1	·
WITHIN:	12-18-049-01 W	1	
LICENCEE:	DEVON ARL CO	RPORATION	
SPUD DATE:	OCTOBER 2, 1999	FINAL DRILL DATE:	OCTOBER 5, 1999 ,
STATUS:	CR-OIL PUMP	ABANDONED DATE:	
SURFACE:		DOWNHOLE:	
OFFSETS:	S 750 E 52	OFFSETS:	S 750 E 52
LATITUDE:	53.227621	LATITUDE:	53.227621
LONGITUDE:	110.150847	LONGITUDE:	110.150847
GROUND ELEVATION:	677.5 m	TOTAL DEPTH:	665 m
WELL ID:	B0 / 14-18-049-0	1 W4 / 0	
LICENCE #:	0014095	LICENCE DATE:	OCT 9, 1957
WELL NAME:	EXCELSIOR DE	VONIA LLOYD 14B-18-	
WITHIN:	14-18-049-01 W4		- garangangan yang ayank kanasaka a Malaki anadi Mari adama apakada ka kada karak anak anak anak a
LICENCEE:	KODIAK PETRO	LEUMS LTD.	
SPUD DATE:	OCTOBER 18, 1957	FINAL DRILL DATE:	OCTOBER 22, 1957
STATUS:	ABD	ABANDONED DATE	OCTOBER 23, 1957
SURFACE:		DOWNHOLE:	
OFFSETS:	S 301.8 E 502.9	OFFSETS:	S 301.8 E 502.9
		I A TOTAL LOCK	50 001651
LATITUDE:	53.231651	LATITUDE:	53.231651
LATITUDE: LONGITUDE:	53.231651 110.144103	LONGITUDE:	110.144103

CRUDE OIL/BITUMEN					A)	/ERAGE D	AILY PRO	DUCTION	RATE				***********
UNIQUE WELL ID	YEAR	JAN	FEB	MAR	APR	MAY	JUN	JUL	AUG	SEPT	OCT	NOV	DEC
100/11-18-049- 01W4/0	2000	0	0	0	0	0	0	0	0	0	1.47	3.299	12.41
na nagang ngayag na sarawana sa sa sa sa na	2001	8.129	14.075	5.527	4.403	0	0	0	0	0	0	0	0
100/12-18-049- 01W4/0	1999	0	0	0	0	0	0	0	0	0	0	1.064	4.026
	2000	3.206	5,316	4.594	4.333	5.63	2.404	2.961	5.339	0	2.948	3,441	2.037
	2001	3.006	1,185	0	0	0	0	0	0	0	0	0	0
manufungs manufungs and dispersion of the first manufungs to the first manufungs to	2002	0	0	0	0	1.465	1.927	1.897	1	1.066	2.8	1.782	0
A80		Naga 44 g						AVÆÐ A	GE DAILY	DBODUS	1081 D 6 7		
GAS UNIQUE WELL ID	YEAR	JAN	FEB	MAR	APR	MAY	JUN	JUL	AUG	SEPT	OCT		DEA
Went of the second seco	TEAR	JAN .	FED	WAR	APR	IVIAT	JUN	JUL	AUG	SEFI	UCI	NOV	DEC
100/11-18-049- 01W4/0	2000	0	0	0	0	0	0	0	0	0	0.005	0.011	0.043
	2001	0.057	0.1	0.036	0.028	0	0	0	0	0	0	0	0
100/12-18-049- 01W4/0	1999	0	0	0	0	0	0	0	0	0	0	0.054	0.2
THE THE PROPERTY OF THE PROPER	2000	0.159	0.267	0.229	0.217	0.282	0.121	0.148	0.269	0	0.148	0.17	0.103
The second secon	2001	0.345	0.135	0	0	0	0	0	0	0	0	0	0
	2002	0	0	0	0	0.229	0.19	0.184	0.123	0.072	0.132	0.071	0
	**************************************		0 - 104 Bullioto Nichbaust-waker Pauls Bastr :					AIFFA	05:54H V	556516	to be a second		
WATER					A PARTY				GE DAILY				
UNIQUE WELL ID	YEAR	JAN	FEB	MAR	APR	MAY	JUN :	JUL	AUG	SEPT	OCT	NOV	DEC
100/11-18-049- 01W4/0	2000	0	0	0	0	0	0	0	0	0	1.44	3.15	6.184
The second secon	2001	8.3	7.25	5.273	0	0	0	0	0	0	0	0	0
100/12-18-049- 01W4/0	1999	0	0	0	0	0	0	0	0	0	0	0.914	0
	2000	0.979	1.247	0.935	0.6	1.408	2.279	0.945	0	3.206	0.91	0	2.88
	2001	1.884	1.081	0	0	0	0	0	0	0	0	0	0
	2002	0	0	1.261	1.933	2.303	0.977	2.865	1.913	1.032	1.364	1.694	2.069

h:

PRINT REPORT VIEW IN EXCEL GLOSE REPORT

WELL ID:	00 / 01-24-049-02 V	V4/2				
LICENCE #:	0284842	LICENCE DATE:	MARCH 21, 2003			
WELL NAME:	HUSKY 1B LLOYDMINSTER 1-24-49-2					
WITHIN:	01-24-049-02 W4					
LICENCEE:	HUSKY OIL OPERA	ATIONS LIMITED				
SPUD DATE:	JUNE 18, 2003	FINAL DRILL DATE:	JUNE 20, 2003			
STATUS:	CR-OIL PUMP	ABANDONED DATE:				
SURFACE:		DOWNHOLE:				
OFFSETS:	N 99.6 W 302	OFFSETS:	N 99.6 W 302			
LATITUDE:	53.235252	LATITUDE:	53.235252			
LONGITUDE:	110.156457	LONGITUDE:	110.156457			
GROUND ELEVATION:	665.6 m	TOTAL DEPTH:	660 m			

WELL ID:	C0 / 01-24-049-02 W	/4 / 0				
LICENCE #:	0014088	LICENCE DATE:	OCTOBER 7, 1957			
WELL NAME: EXCELSIOR DE		VONIA LLOYD 1C-24-49-2				
WITHIN:	01-24-049-02 W4					
LICENCEE: EXCELSION		OR REFINERIES LIMITED				
SPUD DATE:	OCTOBER 11, 1957	FINAL DRILL DATE:	OCTOBER 15, 1957			
STATUS:	ABD	ABANDONED DATE:	OCTOBER 16, 1957			
SURFACE:		DOWNHOLE:				
OFFSETS:	N 321.6 W 301.8	OFFSETS:	N 321.6 W 301.8			
LATITUDE:	53.237246	LATITUDE:	53.237246			
LONGITUDE:	110.156457	LONGITUDE:	110.156457			
GROUND ELEVATION:	666.3 m	TOTAL DEPTH:	633.4 m			

EUB WELL INFORMATION CURRENT TO JANUARY 31, 2006

CRUDE OIL/BITUN	1EN					AVER	AGE D	AILY F	RODUCT	TION RATE	
UNIQUE WELL ID	YEAR	JANUARY	FEBRUARY	MARCH	APRIL	MAY	JUNE	JULY	AUGUST	SEPTEMBER	OCT
100/01-24-049-02W4/2	2003	0	0	0	0	0	0	0	0	0	
	2004	8.184	8.217	7.619	8.741	8.323	9.233	11.422	9.642	11.163	11.
	2005	9.661	9.789	10.3	0	8.345	5.858	2,432	2.923	3.057	1.0
GAS						\VER/	AGE D	AILY F	RODUCT	ION RATE	******
UNIQUE WELL ID	YEAR	JANUARY	FEBRUARY	MARCH	APRIL	MAY	JUNE	JULY	AUGUST	SEPTEMBER	OCTO
100/01-24-049-02W4/2	2003	0	0	0	0	0	0	0	0	0	(
	2004	0.064	0.066	0.274	0.315	0.3	0.333	0.41	0.348	0.403	0.4
	2005	0.348	0.354	0.371	0	0.3	1.247	0.519	0.623	0.733	0.2
						VER	AGE D	AILY F	RODUCT	ION RATE	······
WATER											
WATER UNIQUE WELL ID	YEAR	JANUARY	FEBRUARY	MARCH	APRIL	MAY		JULY		SEPTEMBER	ОСТО
UNIQUE WELL ID	YEAR 2003	JANUARY 0	FEBRUARY 0	MARCH 0						SEPTEMBER 0	OCTO
WATER UNIQUE WELL ID 100/01-24-049-02W4/2					APRIL.	MAY	JUNE	JULY	AUGUST		OCT(

APPENDIX E

STANDARD TERMS AND CONDITIONS



AMEC EARTH & ENVIRONMENTAL, a division of AMEC Americas Limited STANDARD TERMS AND CONDITIONS

- 1) ENTIRE AGREEMENT. Upon authorization by the CLIENT and commencement of performance hereunder, these terms constitute the entire agreement between the parties concerning its subject matter. Any changes or additional conditions proposed by CLIENT are hereby rejected, unless expressly stated in the Agreement or incorporated by a change order.
- 2) CHANGES. Upon receipt of notice from CLIENT of a change in the scope of the work hereunder, AMEC will promptly notify the CLIENT if there is an impact on the schedule, price or terms of the agreement. Thereafter, an estimate of any impact on the contract will be prepared and submitted to the CLIENT. The parties agree to promptly negotiate and implement changes to the Agreement. CLIENT acknowledges and agrees that it's use of any purchase order or other form to procure services is solely for administrative purposes and in no event shall AMEC be bound to any terms and conditions on such form regardless of reference to or signature. CLIENT shall endeavor to reference this Agreement on any purchase order (or any other form), but CLIENT's failure to do so shall not operate to modify this Agreement.
- 3) SITE INFORMATION AND ACCESS. The CLIENT shall make available to AMEC all relevant information and documents under his control regarding past, present and proposed conditions of the site. The information shall include, but not be limited to, plot plans, topographic surveys, hydrologic data and previous soil and geologic data including borings, field or laboratory tests and written reports. The CLIENT shall immediately transmit to AMEC any new information that becomes available or any change in plans. The CLIENT shall also ensure uninterrupted site access for AMEC throughout performance of this Agreement.
- 4) PERMITS AND UTILITIES. Unless otherwise stated elsewhere, the CLIENT shall apply for and obtain all required permits and licenses and shall make all necessary arrangements for right of entry to provide AMEC access to the site for all equipment and personnel at no charge to AMEC. The CLIENT shall also provide AMEC with the location of all underground utilities and structures in the exploration area. AMEC is not responsible for location or identification of utilities.
- 5) PAYMENT. Unless otherwise stated in the Proposal, invoices will be submitted by AMEC either at the completion of the work or on a monthly basis and will be due and payable on the invoice date. Invoices not paid within thirty (30) days of the invoice date shall be subject to a late fee of one and one-half percent (1.5%) per month computed at 31 days from the date of invoice. In addition, any collection fees, attorney's fees, court costs, and other related expenses incurred by AMEC in the collection of delinquent invoice amounts shall be paid by CLIENT.
- 6) OWNERSHIP RIGHTS. Any documents produced by AMEC shall be the sole property of AMEC. At the request and expense of the CLIENT, AMEC shall provide the CLIENT with copies of any or all drawings, specifications and other documents prepared by AMEC.
- 7) ATTORNEY'S FEES. In the event either party makes a claim or brings an action against the other for any act arising out of the performance or interpretation of this agreement, including the payment of professional fees, the unsuccessful party shall pay all reasonable attorney's fees and legal costs incurred by the prevailing party in such claim or action.
- 8) STANDARD OF CARE. In the performance of professional services, AMEC will use that degree of care and skill ordinarily exercised under similar circumstances by reputable members of its profession practicing in the same or similar localities. No warranty, either express or implied, is made or intended by this agreement or by furnishing oral or written reports of the findings. AMEC is to be liable only for damage proximately caused by the negligence of AMEC. The CLIENT recognizes that subsurface conditions may vary from those encountered at the location where borings, surveys or explorations are made by AMEC and that the data, interpretations and recommendation of AMEC are based solely on the information available to him. AMEC will not be responsible for the interpretation by others of the information developed.
- 9) INSURANCE. AMEC will maintain insurance for this Agreement in the following types: 1) worker's compensation insurance at statutorily required levels, 2) comprehensive general liability (CGL) insurance and 3) automotive insurance.
- 10) ENVIRONMENTAL LIABILITY. Because CLIENT owns operates the site where work is being performed, CLIENT has and shall retain all responsibility and liability associated with the environmental conditions at the site. Unless specifically identified elsewhere, CLIENT'S responsibility and liability includes the handling and disposal of any samples or hazardous materials generated on the site as a result of AMEC's performance hereunder.
- 11) CONSEQUENTIAL DAMAGES, AMEC shall NOT be responsible for any consequential, incidental or indirect damages.
- 12) LIMITATION OF LIABILITY. Notwithstanding any other provision of this Agreement, the total liability of AMEC, its officers, directors and employees for liabilities, claims, judgments, demands and causes of action arising under or related to this Agreement, whether based in contract or tort, shall be limited to the total compensation actually paid to AMEC for the Services or \$50,000, whichever is less. All claims by CLIENT shall be deemed relinquished unless filed within one (1) year after substantial completion of the Services.
- 13) DISPUTES. Any dispute arising hereunder shall first be resolved by taking the following steps, where a successive step is taken if the issue is not resolved at the preceding step: 1) by the technical and contractual personnel for each party performing this Subcontract, 2) by executive management of each party, 3) by mediation, 4) by arbitration if both parties agree or 5) through the court system of the jurisdiction of the AMEC office that entered this Agreement. CLIENT hereby waives the right to trial by jury for any disputes arising out of this Agreement.
- 14) WARRANTY OR AUTHORIZATION TO SIGN. The person signing this contract warrants that he has authority to sign as, or on behalf of, the CLIENT for whom or for whose benefit AMEC's services are rendered. If such a person does not have such authority, he agrees that he is personally liable for all breaches of this contract, and that in any such action against him for breach of such warranty, reasonable attorney's fees and legal costs shall be included in a judgement rendered.
- 15) ASSIGNMENT. Neither Client nor AMEC shall assign its interest in this Agreement without the written consent of the other except that AMEC may assign its interest in the Agreement to related or affiliated companies of AMEC without the consent of Client.
- 16) CHOICE OF LAWS. This Agreement shall be governed by the laws of the province of AMEC's office performing the work.



#1500 Baker Centre 10025-106 Street Edmonton, Alberta, Canada T5J 1G3 Phone: (780) 482-2557 Fax: (780) 482-2538

e-mail: <u>dave.martz@sameng.com</u> Website: www.sameng.com

February 28, 2006

Our File: 785

Lorie and Glenda Peregrym P.O. Box 96 Blackfoot, Alberta T0B 0L0

Attention: Lorie and Glenda Peregrym

Dear Mr. & Mrs. Peregrym:

Re: Stormwater Management Plan for Proposed Subdivision, SW 19–49 R1 W4M

The landowner of the above referenced parcel is currently developing a plan to subdivide. The parcel will be subdivided into 30 residential lots, each with an approximate area of 1.2 hectares. The County of Vermilion River #24 requires a Stormwater Management Plan be completed before the subdividing can proceed. The landowner has commissioned Sameng Inc. to analyze the stormwater runoff behavior of the current and the developed parcel and recommend Best Management Practices to mitigate any possible impacts. The following outlines our methodology, findings and recommendations.

The parcel being subdivided covers approximately 45.4 hectares. The parcel and surrounding properties are mostly under agricultural cultivation with only a few residential sites in the vicinity. The major drainage feature in the area is Devonia Lake, which borders the northeast corner of this parcel. A conceptual site plan can be seen in Fig 1.1.

With subdividing this parcel, the amount of structures and infrastructure will increase; therefore the amount of impermeable surface will increase as the natural ground cover is replaced. The subdivision will be accessed from the existing Range Road 20, which runs north-south adjacent to the west side of the parcel. The individual lots will have accesses off the proposed road within the subdivision. Therefore, the new impermeable ground cover will be from new buildings, the new roadway within the subdivision, and lot accesses.

This decrease in permeable surfaces will result in an increase in runoff volumes. The proposed subdividing of this parcel will create 30 country residential lots; therefore the amount of increased runoff is not expected to be substantial. Based

on developed land imperviousness, the permeable ground cover is expected to decrease by 9.8% when the lots are fully developed.

This parcel currently conveys on-site and off-site drainage, see Fig 1.2 for a sketch of the drainage area considered, with the runoff flowing overland in a southwest to northeast direction. The parcel is a contributing area to Devonia Lake which has a constructed outlet to Blackfoot Creek that is licensed to the County of Vermillion River No. 24. There are currently no discernible flow paths in the property but the roadway and accompanying ditch construction will follow the general topography of the area.

To analyze the runoff behavior of this parcel, the increase in Devonia Lake water levels was investigated. A 1:100 year return period with a 24 hr rainfall event based on a Huff Distribution was utilized in this investigation. The increase in flow volume has been calculated assuming no outflow from Devonia Lake and the results are summarized in the table below:

Storm Frequency	Net Increase in Devonia
	Lake Water Levels
1:2 year	2.1mm
1:5 year	3.0mm
1:100 year	5.6mm

These values represent the maximum possible theoretical amount the lake levels could rise in such a storm event.

However, considering the shape of the basin and the fact that the proposed subdivision is adjacent to the lake while other larger contributing areas are farther away with a longer time of concentration, the peak runoff from the subdivision will occur well in advance of the larger runoff flows that would enter the lake from other contributing areas. Also, the theoretical values tabulated above are based on no outflow out of the lake however, in reality an outflow would exist, further decreasing the effects of the increased flow volume. Therefore it is likely that the lake, which has an area of approximately 101.4 hectares, would see no discernible increase in peak water levels with the development of this subdivision. Based on this, we conclude that Devonia Lake is an adequate outlet for this proposed development.

Also, based on the Blackfoot Devonia Water Management Preliminary Engineering Report, the 1:100 year lake level would be 656.1, as shown in Fig 1.1, and this would intrude very little on proposed development.

However, even though the water levels will not greatly increase, certain mitigation measures should be implemented to ensure the increased volume as well as the water quality do not become issues for this subdivision. The ditches along the proposed roadway will accommodate most of the excess volume as well as provide a buffer zone to decrease the flow rate of the water. To address increased

sediment issues, the ditches will be regrassed after the grading is complete to create a sediment trap and prevent erosion. Another measure that will lessen the impacts of the increased sediment is to incorporate two sediment micropools at the proposed outlets to the lake, as can be seen in Fig 1.1. These micropools will have a live storage of 125m³ each and based on a HEC-HMS model for a 1:2 year storm, 100% of sediment 75 microns or larger will be removed. Please refer to Fig 1.3 for a typical cross section of a sediment micropool. These micropools will be low maintenance and will need to be cleaned out once every 10 to 20 years. Two locations have been recommended for ditches leading to these sediment ponds, with culverts that should be no smaller than 500mm, thus complying with County of Vermillion River #24 specifications. These locations were chosen based on the existing topography thus the ditches along the roads should transport the flow without much alteration to the land profile. We also recommend transferring the control of the lands used for the sediment micropools as well as the connecting ditches to the County via a P.U.L., easement or Municipal Reserve.

The locations proposed for the ditches and sediment micropools are for conceptual purposes only. The final design and exact location may need to be modified based on the finalized layout.

Also, the following Best Management Practices are recommended:

- Keep disturbed lands to a minimal in order to minimize erosion potential due to overland flow,
- Minimize the amount of flow in internal lot road ditches. The road ditches should be lined for erosion protection where required.
- Provide a buffer around Devonia Lake of at least 30 meters to protect its shoreline and water quality.
- Ensure all buildings are at least one meter above 1:100 year lake levels of 656.1.
- Complete proper lot grading around buildings to ensure positive drainage away from buildings.

We do not believe that the works proposed here require licensing from Alberta Environment and by copy of this letter invite their comments. As all proposed works are not within the 1:100 year flood level of the lake, there should be no impact on possible fish habitat.


In conclusion, this parcel requires some mitigation due to the increase in volume. These measures, along with the above mentioned best management practices, will sufficiently mitigate the excess water.

Sincerely,

David Martz, P.Eng. Sameng Inc.

pg/DM

cc Doug Jeremy, Alberta Environment






Client	LORIE & GLENDA PEREGRYM	
Project	PEREGRYM SWMP	
Title	DRAINAGE AREA	

Designed By -	Scole N.T.S.	
Checked By D. MARTZ	Drawing No.	
Drawn By PJG	FIGURE 1.2	
Dote FEB 2006	FIGURE 1.2	






SECTION A-A: TYPICAL SEDIMENT MICROPOOL



Client	LORIE & GLENDA PEREGRYM	
Project	PEREGRYM SWMP	
TUE TYPICAL SEDIMENT MICROPOOL		
	CROSS SECTION	

Designed By -	Scole N.T.S.
Checked By D. MARTZ	Orawing No.
Drawn By PJG	FIGURE 1.3
Dote FEB 2006	FIGURE 1.3



Staging Plan

Lake View Estates will have 30 Country Residential lots that will be developed according to the following Phase Plan.

Phase I

Will consist of 7 parcels adjacent to RR20. These are Block 2, Lots 1-6 and Block, Lot 1 and Lot 16.

Service in this order will allow for construction of both entrances off RR20. With the paving of RR20, this will prevent damage to the surfacing project if entrance construction were done a later date.

In addition, clay will be required for the road. It will be serviced from;

- 1) Lots B2 L1 and B2 L2
 - Along RR20 is a ridge that, when cut down, will add to the aesthetics of these 2 lots, as well as provide a short haul source of road construction material.
 - Additional road construction material will be sourced at the settling pond located on the Municipal Reserve Land.

Phase II

Will consist of 8 lots:

- B1 L2 and B1 L3
- B2 (L7, L8, L13, L14)
- B1 L15, B1 L16

Road materials will cost effectively be sources from the settling pond on the Municipal Reserve and by cutting hilltops.

There should be little interference with existing acreages.

Phase III

Will consist of 7 lots;

- B2 L9, B2 L10
- B1 (L4, L5, L6, L7, L8)

Again, the impact on existing acreages should be minimal. Road materials will come from settling ponds, hilltops or cutting of ditches.

Phase IV

Will consist of 7 lots;

- B2 L11, B2 L12
- B1 (L9, L19, L11, L12, L13)



- Phase I
- Phase II
- Phase III

Phase IV

Signage

A low maintenance sign would be constructed as part of the development along RR20 on B2 L3 featuring the LakeView Estate Development $\,$